SAFETY DATA SHEET



1. Identification

Product identifier FUSECRETE C; FUSECRETE C WF

Other means of identification

Brand Code 5326, 5327

Recommended use For Industrial Use Only

Recommended restrictionsUsers should be informed of the potential presence of respirable dust and respirable crystalline

silica as well as their potential hazards. Appropriate training in the proper use and handling of this

material should be provided as required under applicable regulations.

Manufacturer/Supplier information

Manufacturer

Company name HarbisonWalker International

Address 1305 Cherrington Parkway, Suite 100

Moon Township, Pennsylvania 15108 US

Telephone General Phone: 412-375-6600

Website www.thinkHWI.com

Emergency phone number CHEMTREC 24 HOUR 1-800-424-9300

EMERGENCY #

2. Hazard(s) identification

Physical hazards Not classified.

Health hazards Carcinogenicity Category 1

Environmental hazards Not classified.

OSHA defined hazards Not classified.

Label elements



Signal word Danger

Hazard statement May cause cancer.

Precautionary statement

Prevention Obtain special instructions before use. Do not handle until all safety precautions have been read

and understood. Wear protective gloves/protective clothing/eye protection.

Response If concerned: Get medical advice/attention.

Storage Store locked up.

Disposal Dispose of contents/container in accordance with local/regional/national/international regulations.

Hazard(s) not otherwise

classified (HNOC)

None known.

Supplemental information

Users should be informed of the potential presence of respirable dust and respirable crystalline silica as well as their potential hazards. Overexposure to the respirable dust of crystalline silica (quartz or cristobalite, less than or equal to 5 microns in size) may lead to silicosis in humans, which is a progressive and irreversible lung disease. Appropriate training in the proper use and handling of this material should be provided as required under applicable regulations. Users should be informed of the potential presence of respirable dust and respirable crystalline silica as well as their potential hazards. Overexposure to the respirable dust of crystalline silica (quartz or cristobalite, less than or equal to 5 microns in size) may lead to silicosis in humans, which is a progressive and irreversible lung disease. Appropriate training in the proper use and handling of this material should be provided as required under applicable regulations.

3. Composition/information on ingredients

Mixtures

Chemical name	Common name and synonyms	CAS number	%
Aluminium Oxide (Non-Fibrous)		1344-28-1	80 - 90
Cement, Alumina, Chemicals		65997-16-2	2.5 - 10
Chromium (III) oxide		1308-38-9	2.5 - 10
Silicon Dioxide		7631-86-9	1 - 2.5
Titanium Dioxide		13463-67-7	1 - 2.5
Cristobalite		14464-46-1	0.1 - 1
Other components below reportable le	vels		1 - 2.5

^{*}Designates that a specific chemical identity and/or percentage of composition has been withheld as a trade secret.

4. First-aid measures

Move to fresh air. Call a physician if symptoms develop or persist. Inhalation

Skin contact Wash off with soap and water. Get medical attention if irritation develops and persists. Eye contact Do not rub eyes. Rinse with water. Get medical attention if irritation develops and persists.

Rinse mouth. Get medical attention if symptoms occur. Ingestion Dusts may irritate the respiratory tract, skin and eyes. Most important

symptoms/effects, acute and delayed

Indication of immediate medical attention and special treatment needed

Provide general supportive measures and treat symptomatically. Keep victim under observation. Symptoms may be delayed.

General information If concerned: Get medical advice. Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves.

5. Fire-fighting measures

Suitable extinguishing media

Unsuitable extinguishing media

Use fire-extinguishing media appropriate for surrounding materials.

Not available.

Specific hazards arising from the chemical

Not applicable.

Special protective equipment and precautions for firefighters Not available.

6. Accidental release measures

Personal precautions. protective equipment and emergency procedures

Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Wear appropriate protective equipment and clothing during clean-up. Use a NIOSH/MSHA approved respirator if there is a risk of exposure to dust/fume at levels exceeding the exposure limits. Ensure adequate ventilation. Local authorities should be advised if significant spillages cannot be contained. For personal protection, see section 8 of the SDS.

Methods and materials for containment and cleaning up Stop the flow of material, if this is without risk. Collect dust using a vacuum cleaner equipped with HEPA filter.

Large Spills: Wet down with water and dike for later disposal. Shovel the material into waste container. Avoid the generation of dusts during clean-up. Following product recovery, flush area with water.

Small Spills: Sweep up or vacuum up spillage and collect in suitable container for disposal. For waste disposal, see section 13 of the SDS.

Environmental precautions

Avoid discharge into drains, water courses or onto the ground.

7. Handling and storage

Precautions for safe handling

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Minimize dust generation and accumulation. Provide appropriate exhaust ventilation at places where dust is formed. Do not breathe dust. Avoid prolonged exposure. Should be handled in closed systems, if possible. Wear appropriate personal protective equipment. Observe good industrial hygiene practices.

Conditions for safe storage. including any incompatibilities Store locked up. Store in original tightly closed container. Store in a well-ventilated place. Store away from incompatible materials (see Section 10 of the SDS).

8. Exposure controls/personal protection

Occupational exposure limits

should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	Components	for Air Contaminants (29 CFR 1910.1000) Type	Value	Form
Chromium (III) oxide (CAS PEL 0.5 mg/m3 10 dist. 1308-38-9) 15 mg/m3 15 tel dust. 1308-38-9) 15 mg/m3 15 tel dust. 1348-367-7) 15 mg/m3 15 tel dust. 1348-367-7	(Non-Fibrous) (CAS	PEL	5 mg/m3	Respirable fraction.
1308-39-9) Titanium Dioxide (CAS 1910.1000) Components Type Value Form Cristobalite (CAS 10.0 time Type 10.0 mpm; Acespirable (CAS 14464-46-1) Silicon Dioxide (CAS 10.0 time Type 10.0 mpm; Acespirable (CAS 10			15 mg/m3	Total dust.
13463-67-7) US. OSHA Table Z-3 (29 CFR 1910.1000) Type		PEL	0.5 mg/m3	
Components Type Value Form Cristobalite (CAS TWA 0.15 mg/m3 Total dust. 14464-46-1) 0.05 mg/m3 Respirable. Silicon Dioxide (CAS TWA 0.8 mg/m3 Respirable. 7531-86-9) 20 mppcf USA CGIH Threshold Limit Values Type Value Form Aluminium Oxide (Non-Fibrous) (CAS TWA 1 mg/m3 Respirable fraction. Aluminium Oxide (Non-Fibrous) (CAS TWA 0.5 mg/m3 Respirable fraction. Aluminium Oxide (CAS TWA 0.5 mg/m3 Respirable fraction. Aluminium Oxide (CAS TWA 0.5 mg/m3 Respirable fraction. Aluminium (III) oxide (CAS TWA 10 mg/m3 And Total dust. Aluminium (III) oxide (CAS TWA 10 mg/m3 And Total dust. Components Type Value Form Chromium (III) oxide (CAS TWA 3 fibers/cm3 Dust. Aluminium (III) oxide (CAS TWA 3 fibers/cm3 Dust. Aluminium (III) oxide (CAS TWA 3 fibers/cm3<		PEL	15 mg/m3	Total dust.
Cristobalite (CAS 14464-46-1) Cristobalite (CAS 14464-46-1) Cristobalite (CAS 14464-46-1) Cristobalite (CAS 14464-46-1) Silicon Dioxide (CAS 7WA 0.8 mg/m3 7631-86-9) Cristobalite (CAS 7WA 0.8 mg/m3 7631-86-9) Cristobalite (CAS 7WA 0.8 mg/m3 7631-86-9) Cristobalite (CAS 7WA 1 mg/m3 7 Respirable. Components 7WA 1 mg/m3 7 Respirable. Components 7WA 1 mg/m3 7 Respirable fraction. Components 7WA 1 mg/m3 7 Respirable fraction. Components 7WA 1 mg/m3 7 Respirable fraction. Components 7WA 0.5 mg/m3 7 Respirable fraction. Cristobalite (CAS 7 WA 0.025 mg/m3 7 Respirable fraction. Cristobalite (CAS 7 WA 0.025 mg/m3 7 Respirable fraction. Cristobalite (CAS 7 WA 0.025 mg/m3 7 Respirable fraction. Components 7WA 0.5 mg/m3 7 Respirable fraction. Components 7WA 0.5 mg/m3 Fiber. Cristobalite (CAS 7 WA 0.5 mg/m3 Fiber. Cristob				_
14464-46-1) Silicon Dioxide (CAS TWA 0.8 mg/m3 Respirable. 1.2 mppcf Respirable. 1.2 mppcf Value Form Aluminium Oxide TWA 1 mg/m3 Respirable fraction. Non-Fibrous) (CAS TWA 0.5 mg/m3 Respirable fraction. Non-Fibrous) (CAS 1 mg/m3 Respirable fraction. Non-Fibrous (CAS 1 mg/m3 mg/m3 Respirable fraction. Non-Fibrous (CAS 1 mg/m3 mg/m3 Respirable fraction. Non-Fibrous (CAS 1 mg/m3 mg/	Components	Туре	Value	Form
Silicon Dioxide (CAS TWA 0.8 mg/m3 7631-86-9) US. ACGIH Threshold Limit Values Components Type Value Form Aluminium Oxide (Non-Fibrous) (CAS 1 MA 1 mg/m3 Respirable fraction. (Non-Fibrous) (CAS 1 MA 0.5 mg/m3 1284-28-1) Chromium (III) oxide (CAS TWA 0.25 mg/m3 Respirable fraction. (Non-Fibrous) (CAS 1 MA 0.5 mg/m3 13463-67-7) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Chromium (III) oxide (CAS TWA 0.5 mg/m3 1360-8-39) Cristobalite (CAS TWA 3 fibers/cm3 Piber. (14464-46-1) Silicon Dioxide (CAS TWA 3 fibers/cm3 Fiber. (14464-46-1) Silicon Dioxide (CAS TWA 6 mg/m3 fibers, total dust 5 mg/m3 fibers, total dust 6 mg/m3 fibers (14464-46-1) Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be monitored and controlled. Or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels below recommended exposure limits engineering measures are not sufficient to maintain concentrations of dust particulates below the oxidual protection measters, such as personal protective equipment Eyelface protection (Mear appropriate chemical resistant gloves.) Skin protection Hand protection Wear appropriate chemical resistant gloves.		TWA	0.15 mg/m3	Total dust.
Silicon Dioxide (CAS 7631-86-9) US. ACGIH Threshold Limit Values Components Type Value Form TWA 1 mg/m3 Respirable fraction. (Non-Fibrous) (CAS 1344-28-1) Chromium (III) oxide (CAS 7WA 0.5 mg/m3 1308-38-9) Cristobalite (CAS 7WA 0.025 mg/m3 Respirable fraction. 14464-46-1) TITAIN 10 mg/m3 Respirable fraction. 14464-46-1) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Chromium (III) oxide (CAS 7WA 0.5 mg/m3 Respirable fraction. 14464-46-1) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Chromium (III) oxide (CAS 7WA 0.5 mg/m3 Respirable fraction. 1308-38-9) Chromium (III) oxide (CAS 7WA 0.5 mg/m3 Fiber. 1308-38-9) Chromium (III) oxide (CAS 7WA 0.5 mg/m3 Fiber. 1318-6-9) Ogical limit value No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Occupational Exposure Limit (DEL), suitable respiratory protection must be worm. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. Vidual protection measures, such as personal protective equipment Eye/face protection Wear appropriate chemical resistant gloves.	·		•	
Togonoents US. ACGIH Threshold Limit Values Components Type Value Form Aluminium Oxide (Non-Fibrous) (CAS 1344-28-1) Chromium (III) oxide (CAS 1344-28-1) Ciristobalite (CAS 1308-38-9) Cristobalite (CAS 1 TWA 10 mg/m3 1008-38-9) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Value Form Value Form Titanium Dioxide (CAS 1 TWA 10 mg/m3 13463-67-7) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form TWA 10 5 mg/m3 1308-38-9) Cristobalite (CAS 1 TWA 3 fibers/cm3 5 mg/m3 Fiber. 13463-46-1) Sillicon Dioxide (CAS 1 TWA 3 fibers/cm3 5 mg/m3 Fiber, total 5 mg/m3 Fiber, total 5 mg/m3 Fibers, total dust 6 mg/m3 7631-86-9) Ogical limit values Occupational exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Occupational exposure to nuisance dust (total and respirable one respirable crystalline silica should be monitored and controlled. Occupational exposure to nuisance dust (total and respirable moure should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. Volcupational Exposure Limit (DEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. Volcupational Exposure Limit (DEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation of which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits.			• •	Respirable.
US. ACGIH Threshold Limit Values Components Type Value Form Aluminium Oxide (Non-Fibrous) (CAS 1344-28-1) Chromium (III) oxide (CAS 1304-28-1) Chromium (III) oxide (CAS 17WA 0.05 mg/m3 1308-38-9) TWA 0.025 mg/m3 Respirable fraction. 14464-46-1) Titanium Dioxide (CAS 17WA 0.025 mg/m3 Respirable fraction. 14464-46-1 Titanium Dioxide (CAS 17WA 0.05 mg/m3 Respirable fraction. 14464-46-1 TWA 10 mg/m3 Respirable fraction. 14464-46-1 TWA 0.5 mg/m3 Fiber. 13463-67-7) Chromium (III) oxide (CAS TWA 0.5 mg/m3 Fiber. 1308-38-9) Chromium (III) oxide (CAS 17WA 0.5 mg/m3 Fiber. 1308-38-9) TWA 0.5 mg/m3 Fiber, total 5 mg/m3 Fiber, total 6 mg/m3 Fiber, total dust 6 mg/m3 Fiber, total dust 7 mg/m3 Fiber, total dust 8 mg/m3 Fiber, total dust 8 mg/m3 Fiber, total dust 9 mg/m3 Fiber, total dust 9 mg/m3 Fiber, total dust 9 mg/m3 Fiber, total dust 1 mg/m3 Fiber, total dust 2 mg/m3 Fiber, total dust 3 fibers/cm3 Fiber, total dust 5 mg/m3 Fiber, total dust 6 mg/m3 Fiber, total dust 8 mg/m3 Fiber, total dust 8 mg/m3 Fiber, total dust 9 mg/m3 Fiber, tot		TWA	0.8 mg/m3	
Aluminium Oxide (Non-Fibrous) (CAS 1344-28-1) Chromium (III) oxide (CAS 1308-38-9) Cristobalite (CAS 1308-38-9) Christobalite (CAS 1308-38-9) Chromium (III) oxide (CAS 14464-46-1) Silicon Dioxide (CAS 14464-46-1) Silicon Dioxide (CAS 14464-46-1) Silicon Dioxide (CAS 14464-46-1) Occupational exposure limits noted for the ingredient(s). Osure guidelines Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. ropriate engineering trois Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below it Occupational Exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below it occupations are not sufficient to maintain concentrations of dust particulates below it engineering may operation which may generate dusts, us	7031-00-9)		20 mppcf	
(Non-Fibrous) (CAS 1344-28-1) Chromium (III) oxide (CAS TWA 0.025 mg/m3 Respirable fraction. 1344-28-1) Cristobalite (CAS TWA 0.025 mg/m3 Respirable fraction. 14464-46-1) Titanium Dioxide (CAS TWA 10 mg/m3 13463-67-7) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Chromium (III) oxide (CAS TWA 0.5 mg/m3 Fiber. 1308-38-9) Cristobalite (CAS TWA 3 fibers/cm3 Fiber. 14464-46-1) Chromium (III) oxide (CAS TWA 3 fibers/cm3 Fiber. 14464-46-1) Silicon Dioxide (CAS TWA 3 fibers/cm3 Fiber, total 5 mg/m3 fibers, total dust 5 mg/m3 fibers, total dust 6 mg/m3 fibers, total dust 7 mg/m3 fibers, total dust 7 mg/m3 fibers, total dust 8 mg/m3 fibers, total dust 9 mg/m3 fibers, total fibers, form mg/m3 fibers,			Value	Form
Chromium (III) oxide (CAS TWA 0.5 mg/m3 1308-38-9) Cristobalite (CAS TWA 0.025 mg/m3 Respirable fraction. 14464-46-1) Titanium Dioxide (CAS TWA 10 mg/m3 13463-67-7) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Chromium (III) oxide (CAS TWA 0.5 mg/m3 1308-38-9) Cristobalite (CAS TWA 0.5 mg/m3 Fiber. 14464-46-1) Chromium (III) oxide (CAS TWA 0.5 mg/m3 Fiber. 14464-46-1) Silicon Dioxide (CAS TWA 3 fibers/cm3 Dust. 5 mg/m3 Fiber, total 5 mg/m3 Fiber, total 5 mg/m3 fibers, total dust 6 mg/m3 6 mg/m3 7631-86-9) ogical limit values Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering masures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels to an acceptable level. If engineering measures a	(Non-Fibrous) (CAS	TWA	1 mg/m3	Respirable fraction.
Cristobalitie (CAS TWA 0.025 mg/m3 Respirable fraction. 14464-46-1) Titanium Dioxide (CAS TWA 10 mg/m3 13463-67-7) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Chromium (III) oxide (CAS TWA 0.5 mg/m3 Fiber. 1308-38-9) Cristobalite (CAS TWA 3 fibers/cm3 Fiber. 14464-46-1) Silicon Dioxide (CAS TWA 3 fibers/cm3 Dust. 5 mg/m3 Fiber, total 5 mg/m3 Fiber, total 6 mg/m3 fibers, total dust 6 mg/m3 fibers, total dust 6 mg/m3 fibers, total dust 7631-86-9) ogical limit values Occupational exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Cocupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. Vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	Chromium (III) oxide (CAS	TWA	0.5 mg/m3	
Titanium Dioxide (CAS 13463-67-7) US. NIOSH: Pocket Guide to Chemical Hazards Components Type Value Form Chromium (III) oxide (CAS 7WA 0.5 mg/m3 1308-38-9) Cristobalite (CAS 7WA 3 fibers/cm3 Fiber. 14464-46-1) Silicon Dioxide (CAS 7WA 5 mg/m3 Fiber, total 5 mg/m3 fibers, total dust 5 mg/m3 fibers, total dust 5 mg/m3 fibers, total dust 6 mg/m3 Silicon Dioxide (CAS 7WA 6 mg/m3 fibers, total dust 6 mg/m3 Silicon Dioxide (CAS 7WA 6 mg/m3 fibers, total dust 6 mg/m3 Source guidelines Occupational exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (DEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	Cristobalite (CAS	TWA	0.025 mg/m3	Respirable fraction.
Components Type Value Form Chromium (III) oxide (CAS TWA 0.5 mg/m3 1308-38-9) Cristobalite (CAS 14464-46-1) TWA 3 fibers/cm3 Dust. 5 mg/m3 Fiber, total 5 mg/m3 Fibers, total dust 6 mg/m3 Fibers, total dust 7631-86-9) TWA Occupational exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silical should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain airborne levels be an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the recommended exposure limits. Vidual protection measures, such as personal protective equipment Eye/face protection Wear appropriate chemical resistant gloves.		TWA	10 mg/m3	
Chromium (III) oxide (CAS TWA 0.5 mg/m3 1308-38-9) Cristobalite (CAS TWA 3 fibers/cm3 Fiber. 14464-46-1) Silicon Dioxide (CAS TWA 5 mg/m3 Fiber, total 5 mg/m3 fibers, total dust 5 mg/m3 fibers, total dust 6 mg/m3 Occupational exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below to Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. Vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	US. NIOSH: Pocket Guide to	o Chemical Hazards		
1308-38-9) Cristobalite (CAS 14464-46-1) TWA 3 fibers/cm3 Fiber. 3 fibers/cm3 Dust. 5 mg/m3 Fiber, total 5 mg/m3 fibers, total dust 6 mg/m3 Fosure guidelines Occupational exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Cocupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Wear appropriate chemical resistant gloves.	Components	Туре	Value	Form
Cristobalite (CAS 14464-46-1) TWA 3 fibers/cm3 Fiber. 3 fibers/cm3 Dust. 5 mg/m3 Fiber, total 5 mg/m3 fibers, total dust 6 mg/m3 7631-86-9) Occupational exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Wear appropriate chemical resistant gloves.		TWA	0.5 mg/m3	
Silicon Dioxide (CAS TWA 6 mg/m3 fibers, total dust 5 mg/m3 fibers, total dust 6 mg/m3 fibers, total dust 7631-86-9) ogical limit values No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.		TWA	3 fibers/cm3	Fiber.
Silicon Dioxide (CAS TWA 6 mg/m3 fibers, total dust 6 mg/m3 7631-86-9) ogical limit values No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. oropriate engineering trols Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.				
Silicon Dioxide (CAS 7631-86-9) ogical limit values osure guidelines Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.			- 5	
rogical limit values No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilatio or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. Vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	Cilican Diavide (CAC	TIA/A	•	tibers, total dust
Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. Vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Wear appropriate chemical resistant gloves.	7631-86-9)		ŭ	
should be monitored and controlled. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	-			
should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. exposure limits have not been established, maintain airborne levels to an acceptable level. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection must be worn. If material is ground, cut, or used in any operation which may generate dusts, use appropriate local exhaust ventilation to keep exposures below the recommended exposure limits. vidual protection measures, such as personal protective equipment Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	osure guidelines		al and respirable) and re	spirable crystalline silica
Eye/face protection Chemical respirator with organic vapor cartridge, full facepiece, dust and mist filter. Skin protection Hand protection Wear appropriate chemical resistant gloves.	oropriate engineering trols	should be matched to conditions. If applicable or other engineering controls to maintain airborexposure limits have not been established, mengineering measures are not sufficient to ma Occupational Exposure Limit (OEL), suitable ground, cut, or used in any operation which measures.	e, use process enclosure orne levels below recome aintain airborne levels to aintain concentrations of respiratory protection may generate dusts, use	es, local exhaust ventilation mended exposure limits. on an acceptable level. If fust particulates below thust be worn. If material is appropriate local exhaust
Hand protection Wear appropriate chemical resistant gloves.			lge, full facepiece, dust	and mist filter.
		Wear appropriate chemical resistant gloves.		
	Other	Use of an impervious apron is recommended.		

Respiratory protection

Use a NIOSH/MSHA approved respirator if there is a risk of exposure to dust/fume at levels exceeding the exposure limits.

Thermal hazards

Wear appropriate thermal protective clothing, when necessary.









General hygiene considerations

Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants.

9. Physical and chemical properties

Appearance

Physical state Solid.

Solid Powder. **Form** Color Not available. Odor Not available. **Odor threshold** Not available. нα Not available. Melting point/freezing point Not available. Not available. Initial boiling point and boiling

range

Flash point Not available. Not available. **Evaporation rate** Flammability (solid, gas) Not available. Upper/lower flammability or explosive limits

Flammability limit - lower

(%)

Flammability limit - upper

Not available.

Not available.

Explosive limit - lower (%) Not available. Explosive limit - upper (%) Not available. Not available. Vapor pressure Vapor density Not available. Not available. Relative density

Solubility(ies)

Not available. Solubility (water) Partition coefficient Not available.

(n-octanol/water)

Auto-ignition temperature Not available. **Decomposition temperature** Not available. Viscosity Not available.

10. Stability and reactivity

Reactivity The product is stable and non-reactive under normal conditions of use, storage and transport.

Material is stable under normal conditions. Chemical stability Possibility of hazardous Hazardous polymerization does not occur.

Conditions to avoid

reactions

Contact with incompatible materials.

Incompatible materials Acids. Chlorine.

Incompatibility is based strictly upon potential theoretical reactions between chemicals and may not be specific to industrial application exposure. Contact your sales representative for

clarification.

Material name: FUSECRETE C; FUSECRETE C WF 5326, 5327 Version #: 01 Issue date: 07-29-2015 Hazardous decomposition

No hazardous decomposition products are known.

products

11. Toxicological information

Information on likely routes of exposure

Dust may irritate respiratory system. Prolonged inhalation may be harmful. Inhalation

Skin contact Dust or powder may irritate the skin.

Dust may irritate the eyes. Eve contact

Expected to be a low ingestion hazard. Ingestion

Symptoms related to the physical, chemical and toxicological characteristics Dusts may irritate the respiratory tract, skin and eyes.

Information on toxicological effects

Acute toxicity Not available.

Skin corrosion/irritation Prolonged skin contact may cause temporary irritation. Serious eye damage/eye Direct contact with eyes may cause temporary irritation.

irritation

Respiratory or skin sensitization

Respiratory sensitization Not a respiratory sensitizer.

Skin sensitization This product is not expected to cause skin sensitization.

No data available to indicate product or any components present at greater than 0.1% are Germ cell mutagenicity

mutagenic or genotoxic.

Carcinogenicity In 1997, IARC (the International Agency for Research on Cancer) concluded that crystalline silica

inhaled from occupational sources can cause lung cancer in humans. However in making the

overall evaluation, IARC noted that "carcinogenicity was not detected in all industrial

circumstances studied. Carcinogenicity may be dependent on inherent characteristics of the crystalline silica or on external factors affecting its biological activity or distribution of its polymorphs." (IARC Monographs on the evaluation of the carcinogenic risks of chemicals to humans, Silica, silicates dust and organic fibres, 1997, Vol. 68, IARC, Lyon, France.) In June 2003, SCOEL (the EU Scientific Committee on Occupational Exposure Limits) concluded that the main effect in humans of the inhalation of respirable crystalline silica dust is silicosis. "There is sufficient information to conclude that the relative risk of lung cancer is increased in persons with silicosis (and, apparently, not in employees without silicosis exposed to silica dust in quarries and in the ceramic industry). Therefore, preventing the onset of silicosis will also reduce the cancer risk..." (SCOEL SUM Doc 94-final, June 2003) According to the current state of the art, worker protection against silicosis can be consistently assured by respecting the existing regulatory

occupational exposure limits. May cause cancer. Occupational exposure to respirable dust and

respirable crystalline silica should be monitored and controlled.

IARC Monographs. Overall Evaluation of Carcinogenicity

Chromium (III) oxide (CAS 1308-38-9) 3 Not classifiable as to carcinogenicity to humans.

Cristobalite (CAS 14464-46-1) 1 Carcinogenic to humans.

Silicon Dioxide (CAS 7631-86-9) 3 Not classifiable as to carcinogenicity to humans.

Titanium Dioxide (CAS 13463-67-7) 2B Possibly carcinogenic to humans.

US. National Toxicology Program (NTP) Report on Carcinogens

Cristobalite (CAS 14464-46-1) Known To Be Human Carcinogen.

Reasonably Anticipated to be a Human Carcinogen.

US. OSHA Specifically Regulated Substances (29 CFR 1910.1001-1050)

Not listed.

Reproductive toxicity This product is not expected to cause reproductive or developmental effects.

Specific target organ toxicity -

single exposure

Not classified.

Specific target organ toxicity -

repeated exposure

Not classified.

Aspiration hazard Not an aspiration hazard.

Chronic effects Prolonged inhalation may be harmful. Prolonged exposure may cause chronic effects.

Material name: FUSECRETE C; FUSECRETE C WF 5326, 5327 Version #: 01 Issue date: 07-29-2015

12. Ecological information

Ecotoxicity The product is not classified as environmentally hazardous. However, this does not exclude the

possibility that large or frequent spills can have a harmful or damaging effect on the environment.

No data is available on the degradability of this product. Persistence and degradability

Bioaccumulative potential No data available. Mobility in soil No data available.

No other adverse environmental effects (e.g. ozone depletion, photochemical ozone creation Other adverse effects

potential, endocrine disruption, global warming potential) are expected from this component.

13. Disposal considerations

This product, in its present state, when discarded or disposed of, is not a hazardous waste **Disposal instructions**

according to Federal regulations (40 CFR 261.4 (b)(4)). Under RCRA, it is the responsibility of the user of the product to determine, at the time of disposal, whether the product meets RCRA criteria

for hazardous waste.

Hazardous waste code Not applicable.

Waste from residues / unused

products

As sold, this product is not RCRA hazardous. Final used condition must be evaluated prior to disposal. Dispose of waste product in accordance with Federal, State and Local regulations. The chrome compounds (Cr III) in this product may be altered to a hexavalent compound (Cr VI) under certain use conditions, such as exposure to alkali salts and/or high temperatures. Proper waste testing (such as TCLP)must be done to determine the waste status of used product. Reuse and recycling of chrome Refractories is recommended whenever possible.

Not available. Contaminated packaging

14. Transport information

DOT

Not regulated as dangerous goods.

IATA

Not regulated as dangerous goods.

IMDG

Not regulated as dangerous goods.

Transport in bulk according to Annex II of MARPOL 73/78 and Not applicable.

the IBC Code

15. Regulatory information

US federal regulations This product is a "Hazardous Chemical" as defined by the OSHA Hazard Communication

Standard, 29 CFR 1910.1200. All chemical substances in this product are listed on the TSCA

chemical substance inventory where required.

TSCA Section 12(b) Export Notification (40 CFR 707, Subpt. D)

Not regulated.

CERCLA Hazardous Substance List (40 CFR 302.4)

Not listed.

SARA 304 Emergency release notification

Not regulated.

US. OSHA Specifically Regulated Substances (29 CFR 1910.1001-1050)

Not listed.

Superfund Amendments and Reauthorization Act of 1986 (SARA)

Hazard categories Immediate Hazard - No

Delayed Hazard - Yes Fire Hazard - No Pressure Hazard - No Reactivity Hazard - No

SARA 302 Extremely hazardous substance

Not listed.

SARA 311/312 Hazardous Nο

chemical

5326, 5327 Version #: 01 Issue date: 07-29-2015

SARA 313 (TRI reporting)

Chemical name	CAS number	% by wt.	
Aluminium Oxide (Non-Fibrous)	1344-28-1	80 - 90	
Chromium (III) oxide	1308-38-9	2.5 - 10	

Other federal regulations

Clean Air Act (CAA) Section 112 Hazardous Air Pollutants (HAPs) List

Chromium (III) oxide (CAS 1308-38-9)

Clean Air Act (CAA) Section 112(r) Accidental Release Prevention (40 CFR 68.130)

Not regulated.

Safe Drinking Water Act

Not regulated.

(SDWA)

US state regulations

US. California Controlled Substances. CA Department of Justice (California Health and Safety Code Section 11100)

Not listed.

US. Massachusetts RTK - Substance List

Aluminium Oxide (Non-Fibrous) (CAS 1344-28-1)

Chromium (III) oxide (CAS 1308-38-9)

Cristobalite (CAS 14464-46-1)

Silicon Dioxide (CAS 7631-86-9)

Titanium Dioxide (CAS 13463-67-7)

US. New Jersey Worker and Community Right-to-Know Act

Aluminium Oxide (Non-Fibrous) (CAS 1344-28-1)

Chromium (III) oxide (CAS 1308-38-9)

Cristobalite (CAS 14464-46-1)

Silicon Dioxide (CAS 7631-86-9)

Titanium Dioxide (CAS 13463-67-7)

US. Pennsylvania Worker and Community Right-to-Know Law

Aluminium Oxide (Non-Fibrous) (CAS 1344-28-1)

Cristobalite (CAS 14464-46-1)

Silicon Dioxide (CAS 7631-86-9)

Titanium Dioxide (CAS 13463-67-7)

US. Rhode Island RTK

Aluminium Oxide (Non-Fibrous) (CAS 1344-28-1)

US. California Proposition 65

This product contains a chemical known to the State of California to cause cancer.

US - California Proposition 65 - CRT: Listed date/Carcinogenic substance

Titanium Dioxide (CAS 13463-67-7) Listed: September 2, 2011

International Inventories

country(s).

Country(s) or region	Inventory name	On inventory (yes/no)*
Australia	Australian Inventory of Chemical Substances (AICS)	Yes
Canada	Domestic Substances List (DSL)	Yes
Canada	Non-Domestic Substances List (NDSL)	No
China	Inventory of Existing Chemical Substances in China (IECSC)	Yes
Europe	European Inventory of Existing Commercial Chemical Substances (EINECS)	No
Europe	European List of Notified Chemical Substances (ELINCS)	No
Japan	Inventory of Existing and New Chemical Substances (ENCS)	No
Korea	Existing Chemicals List (ECL)	Yes
New Zealand	New Zealand Inventory	Yes
Philippines	Philippine Inventory of Chemicals and Chemical Substances (PICCS)	No
United States & Puerto Rico	Toxic Substances Control Act (TSCA) Inventory	Yes

^{*}A "Yes" indicates that all components of this product comply with the inventory requirements administered by the governing country(s)

A "No" indicates that one or more components of the product are not listed or exempt from listing on the inventory administered by the governing

16. Other information, including date of preparation or last revision

Issue date 07-29-2015

Version # 01

Disclaimer This information is based on our present knowledge on creation date. However, this shall not

constitute a guarantee for any specific product features and shall not establish a legally valid

contractual relationship.

Revision Information Product and Company Identification: Product Codes

Composition / Information on Ingredients: Ingredients

Toxicological Information: Toxicological Data

Ecological Information: Ecotoxicity

Material name: FUSECRETE C; FUSECRETE C WF 5326, 5327 Version #: 01 Issue date: 07-29-2015